CERTIFICATE OF STORAGE TANK SYSTEM TESTING



Crompco, LLC

1815 Gallagher Road

Plymouth Meeting, PA 19462

Phone: (610) 278-7203 Fax: (610) 278-7621

Work Order #372850	Client Information	Location #USP04014
Date:Wed Aug 20th, 2014	New Jersey Petroleum	New Jersey Petroleum Organization
Reason:Compliance	Organization(Adnan Kiriscioglu)	U.S. Gas
	Invoice #600143	131 WEST MERRICK RD
	Permit#	FREEPORT, NY 11520
	P.O.#	County: Nassau
		State ID: 04-0149

Testing was conducted in accordance with all applicable portions of Federal, NFPA, and local regulations.

Lines					
Equip#	Grade	Test	Result		
12230 (1-6)	Premium	Petro-tite Line	Pass		
12232 (1-6)	Regular	Petro-tite Line	Pass		

Leak Detectors					
Equip#	Grade	Test	Result		
12230	Premium	Leak Detector	Pass		
12232	Regular	Leak Detector	Pass		

Miscellaneous Inspections				
Test	Result			
Shear Valve	Pass			

Additional Costs

PARTS: Check Valve, Functional Element, Syphon Activator

EXPENSES: Fuel Surcharge, Miscellaneous Consumables, Test Results Storage

Brian Sjostrom

Petro-Tite Line Testing# 3000008832 (Exp: 12/02/2015)
Rockland County Approved for Petro-Tite Line Testing
NYC Fire Department Certificate of Fitness# 63662803
Line Testing COF ID# 20000350 Tester ID# 29494 Type: UF

API Worksafe Safety Key# 20015402

Bur Addim

Crompco, LLC
1815 Gallagher Road

Plymouth Meeting PA

U.S. Gas Phone: (610) 278-7203 131 WEST MERRICK RD FREEPORT, NY 11520 Facility/Agency Copy
Site #USP04014 / WO #372850

Wed Aug 20th, 2014

Plymouth Meeting, PA 19462 FAX: 610-278-7621

State ID: 04-0149

Petro Tite Line Test

Line Number:	12230						
Grade:	Premium	Net Volume Change	0.00000 gph				
Material:	Fiberglass	Bleedback					
Line Length:	130 ft.	(PL X Ba) + (FC X Bb) + B = N					
Diameter:	2 in.	(130 x 0.00000) + (4 x 0.00	06) + 0.05 = 0.074 gals				
Testing Line Length:	130						
Dispenser Range	1-6	Allowable (gal)	0.074				
Wall:	Double	Measured (gal)	0.04400				
Pump Manufac:	Red Jacket		Pass				
Type of System:	☐ American Suction ☑ Pressure	Result	Fail Inconclusive				
1		·	1				

Time	Procedure	Pressure (psi)		,	Comments		
Time	Flocedule	Before	After	Before	After	Change	Comments
09:45	Connected line tester to: Shear Valve Port	0.0	0.0	0.0000	0.0000		
10:00	Started line test	0.0	50.0	0.0000	0.0320	N/A	
10:15	Line Test Continued	50.0	50.0	0.0320	0.0320	0	
10:30	Line Test Continued	50.0	50.0	0.0320	0.0320	0	
	Bleed Back	50.0	0.0	0.0320	0.0760	0.044	

Petro Tite Line Test

Lin	ne Number:	12232							
	Grade:	Regular							
	Material:	Fiberglass		Net Vol	ume Cha	ange: 0.0	00000 gph		
Li	ine Length:	130 ft.			Ble	eedback			
	Diameter:	2 in.		(PL	X Ba) +	(FC X Bb) + B = N		
Т	esting Line Length:	130	$(130 \times 0.00000) + (4 \times 0.006) + 0.05 = 0.074 \text{ gals}$						
	Dispenser Range	1-6							
	Wall:	Double	Allowable (gal): 0.074						
Pum	p Manufac:	Red Jacket	Measured (gal): 0.04500						
Туре	of System:	☐ American Suction ☑ Pressure	Result: Pass Fail Inconclusive						
Time		Procedure	2	Pressur	e (psi)		Volume (g	al)	Comments
Tille	Time Procedure			Before	After	Before	After	Change	Comments
09:45	Connected	l line tester to: Shear	Valve Port	0.0	0.0	0.0000	0.0000		
10:00	10:00 Started line test		0.0	50.0	0.0000	0.0220	N/A		
10:15	10:15 Line Test Continued		50.0	50.0	0.0220	0.0220	0		
10:30	Line Test C	Continued		50.0	50.0	0.0220	0.0220	0	
	Bleed Back	Κ		50.0	0.0	0.0220	0.0670	0.045	

Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462

leak on the product line.

U.S. Gas

Phone: (610) 278-7203 **FAX:** 610-278-7621

131 WEST MERRICK RD FREEPORT, NY 11520

State ID: 04-0149

Wed Aug 20th, 2014

Facility/Agency Copy

Site #USP04014 / WO #372850

Line Leak D	etector Test	Line Leak D	etector Test
Leak Detector Number:	12230	Leak Detector Number:	12232
Grade:	Premium	Grade:	Regular
Dispenser Range:	1-6	Dispenser Range:	1-6
Make:	Red Jacket	Make:	FE Petro
Model:	FX1V	Model:	STP-MLD
Serial #	1201 0647	Serial #	07010360
✓ Mechanical Electro	onic Interstitial Sensor	✓ Mechanical Electro	onic Interstitial Sensor
Equipment Information (where test was conducted):	1/2	Equipment Information (where test was conducted):	I1/2
Submersible Pump Operating Pressure (psi):	27	Submersible Pump Operating Pressure (psi):	127
Check Valve Holding Pressure (psi):	15	Check Valve Holding Pressure (psi):	114
Bleedback Check (gal):	.0120	Bleedback Check (gal):	.0140
Mechanical Line Leak Detector Step-Through Time (seconds): **Note: not applicable for electronic line leak detectors	3	Mechanical Line Leak Detector Step-Through Time (seconds): **Note: not applicable for electronic line leak detectors	3
Metering Pressure (The pressure at which the mechanical leak detector is in leak sensing position):		Metering Pressure (The pressure at which the mechanical leak detector is in leak sensing position):	11
During actual testing, when simulated leak is induced. The mechanical line leak detector stays in leak search position or the electronic line leak detector sets off an alarm as required by the manufacturer (Yes = pass), (No = fail):	✓ Yes □ No	During actual testing, when simulated leak is induced. The mechanical line leak detector stays in leak search position or the electronic line leak detector sets off an alarm as required by the manufacturer (Yes = pass), (No = fail):	✓ Yes □ No
Result: Pass	Fail Inconclusive	Result: Pass	Fail Inconclusive
Test is conducted by simulating	a calibrated 3.0 GPH at 10 psi	Test is conducted by simulating	a calibrated 3.0 GPH at 10 psi

leak on the product line.

Crompco, LLC

U.S. Gas

131 WEST MERRICK RD

Facility/Agency Copy

Site #USP04014 / WO #372850

1815 Gallagher Road

Plymouth Meeting, PA 19462

Phone: (610) 278-7203 **FAX:** 610-278-7621

FREEPORT, NY 11520 **State ID:** 04-0149

Wed Aug 20th, 2014

	<u> </u>							
Dispenser Shear Valve Inspection								
Overall Re	esult:							
P								
Product S	hear Valves	that do not operate pro	operly:					
Product S	hear Valves	that are not installed/n	nounted properly:					
Dispenser #	Product	Shear Valve Make	Operating Properly	Installed/Mounted Properly	Capped She	ar Valve?	С	omments
1/2	Regular	OPW	Yes	Yes				
1/2	Premium	OPW	Yes	Yes				
3/4	Regular	OPW	Yes	Yes				
3/4	Premium	OPW	Yes	Yes				
5/6	Regular	OPW	Yes	Yes				
5/6	Premium	OPW	Yes	Yes				

Crompco, LLC U.S. Gas 131 WEST MERRICK RD Facility/Agency Copy 1815 Gallagher Road Phone: (610) 278-7203 FREEPORT, NY 11520 Site #USP04014 / WO #372850 Plymouth Meeting, PA 19462 FAX: 610-278-7621 State ID: 04-0149 Wed Aug 20th, 2014 Overfill Alarm Remote Dry Brake **Drop Tank** Rectifier 13 I *****: (6) Containment Sump Monitor DW Fill Well 2 12 Interstitial Compass < ₹⊕ I 10 DISP 11 Fixed Reference Cell Stage 1 w/ Extractor CP Test Station HH. 8 $\overline{\mathbb{O}}$ (0) DISP CP Junction Box 卓 ଭା Road STP 匮 (1) 7 DISP ತ್ರ Emergency Stop Anode (((T ₹ ١ Remote Fill Dry Brake Date: 2014-08-20 8 USP04014 I 0 Work Order #: Location #: CROMPCO

4

Crompco, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462 U.S. Gas Phone: (610) 278-7203

FAX: 610-278-7621

131 WEST MERRICK RD FREEPORT, NY 11520 State ID: 04-0149 Facility/Agency Copy
Site #USP04014 / WO #372850
Wed Aug 20th, 2014

Site Diagram Labels

1: Tank - 12230 8K REG 1

2: Tank - 12231 8K REG 2

3: Tank - 12232 8K PREM

4: Road - S. OCEAN AVE.

5: Road - W. MERRICK RD.

6: Dispenser - 1/2

7: Dispenser - 3/4

8: Dispenser - 5/6

9: Block - OFFICE

10: Block - SERVICE CENTER

11: Tank - Heat-550

12: Tank - Waste-550

13: Tank - Heat-550

Work Ticket #: 372850

Address: 131 WEST MERRICK RD FREEPORT, NY 11520

Station #: USP04014 Service Date: 08/20/2014

Parts Sold

	_			
Quantity Sold	Part Name	Manufacturer	Part #	Description
1	Check Valve	Red Jacket	144-183-5	Red Jacket Standard
1	Functional Element	Red Jacket	323-001-5	
1	Syphon Activator	Red Jacket	188-241-5	

Service Details

Crompco was on site performing testing,
repairs, calibration and/or inspections for the
following reason:

Compliance

◠.	_	m	100	_	n	+~
J	u	ш	m	u	ш	ιz

Gallons Pumped:

Site Arrival Time: 09:00:00

Site Depart Time: 11:00:00

Confirmation

By signing this verification you are agreeing that Crompco LLC performed various compliance testing and/or repairs and replaced parts as listed above.

Printed Name Email Signature

Chirino

- Signature captured
- C Refused to sign
- O No one available to sign